

AirMagnet Survey Express 11.2.0

Release Notes

November 2023

Introduction

AirMagnet Survey Express is a powerful, easy-to-use WLAN site survey tool that empowers WLAN professionals with everything they need to survey any 802.11a/b/g/n/ac/ax wireless network on the 2.4GHz, 5GHz, and 6GHz bands.

This *Release Notes* highlights issues addressed in the 11.2.0 release in addition to the new features.

Bug Fixes

This section covers the defects that have been fixed in this release.

Defect ID	Description
179303985	Incorrect channel width displayed for 802.11ax APs on the 2.4GHz band.
185371971	Max signal strength heatmap is incorrect in some cases.
185808695	When importing AirMapper surveys the placed AP icon is missing after creating a filtered data file.

Known Issues

This section documents the major known issues with this AirMagnet Survey Express 11.2.0 release.

Defect ID	Description
178103361	Survey Report: Deleted section is still included in the body of the report.
182968271	A change in Region/Language causes the floor plan to shift.
181290737	View Per AP: AP Properties Color setting is not saved.
181904334	Incorrect AP Power is shown in AP List section of reports.

Release History

Release Month	Release Version
07/2020	AirMagnet Survey Express 10.0.0
12/2020	AirMagnet Survey Express 10.1.0
01/2021	AirMagnet Survey Express 10.2.0
05/2021	AirMagnet Survey Express 10.3.0
07/2021	AirMagnet Survey Express 10.3.1
11/2021	AirMagnet Survey Express 10.4.0
05/2022	AirMagnet Survey Express 10.5.0
11/2022	AirMagnet Survey Express 11.0.0
07/2023	AirMagnet Survey Express 11.1.0
11/2023	AirMagnet Survey Express 11.2.0

Technical Support

If you need help with this AirMagnet Survey Express 11.2.0 release, contact NetAlly, as follows:

Contact Venue	Description
Web:	https://www.netally.com/support/technical-support/
Phone:	1-844-878-2559 or 1-719-755-0770 and select Option 2

Note: International direct dial phone numbers are available at <https://www.netally.com/contact-us/>.